Applicant: Nagendran A/L C. Nadarajah et al

Serial No.: 10/664,807

Filed: September 17, 2003

Page : 2 of 8

Amendments to the Specification:

Please replace the paragraph beginning at page 4, line 3 as with the following amended paragraph:

Attorney's Docket No.: 16508-002001 / PK/P996/CS/2003(US)

Figure 5[[A]] shows diagrammatic longitudinal and cross-sectional views of a pipe being repaired with a wear plate (optional) wrapped around fibre reinforced wrap, enclosed in sleeves with annular chamber filled with grout.